MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

MONTERO SPARE WHEEL LOCK LOCATION

NO.	TSB-89-31-001
DATE	November, 1989
MODEL	1990 Montero

PURPOSE

This bulletin is issued to advise Service Managers and PDI technicians of a new shipping storage location for the Montero spare wheel lock and nuts.

The lock cylinder assembly and two nuts (Fig. 1) were formerly shipped in the glove box. They are now shipped in a nylon bag inside the tool box under the rear seat, where they may be found for installation during Pre-Delivery Inspection.

This change applies to Monteros built after the end of August, 1989.



FIGURE 1

FILE UNDER: Group 31 Wheels and Tires in the Dealer Service Information Binder. (748)

CIRCULATE TO:

- [Y] SERVICE ADVISOR
- [ ] GENERAL MANAGER
- [Y] SERVICE MANAGER
- [ ] PARTS MANAGER
- [ ] WARRANTY PROCESSOR
- [Y] TECHNICIAN
- [ ] SALES MANAGER

016612